

Major Appliance

Flat Rate Guide

**2005 Edition
Manual 26**

National Independent Appliance
Servicers Association

Major Appliance

Flat Rate Guide

**2005 Edition
Manual 26**

National Independent Appliance
Servicers Association

Table of Contents

Whirlpool Belt Driven Washers.....	pg. 1
Whirlpool Direct-Drive Washers.....	2
General Electric Washers.....	3
Maytag Washers	4
Frigidaire Washers	5
Amana Washers	6
Whirlpool Dryers	7
General Electric Dryers	8
Maytag Dryers	9
Frigidaire Dryers	11
Norge Dryers	12
Refrigerators	13
Icemakers	14
Ovens	15
Ranges	16
Whirlpool Dishwashers	17
General Electric & Maytag Dishwashers.....	18
D & M Dishwashers	19
Microwaves	20
Disposers & Instant Hots	21
Trash Compactors & Water Heaters	22

Table of Contents

Whirlpool Belt Driven Washers.....	pg. 1
Whirlpool Direct-Drive Washers.....	2
General Electric Washers.....	3
Maytag Washers	4
Frigidaire Washers	5
Amana Washers	6
Whirlpool Dryers	7
General Electric Dryers	8
Maytag Dryers	9
Frigidaire Dryers	11
Norge Dryers	12
Refrigerators	13
Icemakers	14
Ovens	15
Ranges	16
Whirlpool Dishwashers	17
General Electric & Maytag Dishwashers.....	18
D & M Dishwashers	19
Microwaves	20
Disposers & Instant Hots	21
Trash Compactors & Water Heaters	22

Whirlpool Belt-Driven Washers
(Kenmore, KitchenAid, Roper & In-Sink-Erator)

Whirlpool Belt-Driven Washers
(Kenmore, KitchenAid, Roper & In-Sink-Erator)

Description of the Job	Price
1) Replace and adjust belt (95405)	\$95.00
2) Replace pump (two hose, 35065)	135.00
3) Replace pump (three hose, 285317)	140.00
4) Replace pump (four hose, 350367)	140.00
5) Pumps and belt together	160.00
6) Replace wig-wag assembly (84867)	125.00
7) Reseal outer tub (with donut seal, 93553 and oversize washer kit, 76673)	165.00
8) Replace fill valve (CW151)	98.00
9) Replace timer knob (355519, 3364290 or 3362624)	78.00
10) Install two speed motor (285222)	230.00
11) Install timer	190.00
12) Spin drive assembly	240.00
13) Replace bearings, seals and clutch	295.00
14) Repair hose or drain fitting leaks (285743)	95.00
15) Replace sheared drive block (389140 or 96384)	145.00
16) Replace lid safety switch	120.00
17) Replace off-balance switch (350780)	125.00
18)	
19)	

Description of the Job	Price
1) Replace and adjust belt (95405)	\$95.00
2) Replace pump (two hose, 35065)	135.00
3) Replace pump (three hose, 285317)	140.00
4) Replace pump (four hose, 350367)	140.00
5) Pumps and belt together	160.00
6) Replace wig-wag assembly (84867)	125.00
7) Reseal outer tub (with donut seal, 93553 and oversize washer kit, 76673)	165.00
8) Replace fill valve (CW151)	98.00
9) Replace timer knob (355519, 3364290 or 3362624)	78.00
10) Install two speed motor (285222)	230.00
11) Install timer	190.00
12) Spin drive assembly	240.00
13) Replace bearings, seals and clutch	295.00
14) Repair hose or drain fitting leaks (285743)	95.00
15) Replace sheared drive block (389140 or 96384)	145.00
16) Replace lid safety switch	120.00
17) Replace off-balance switch (350780)	125.00
18)	
19)	

(1)

Whirlpool Direct-Drive Washers
(Kenmore, KitchenAid, Roper & In-Sink-Erator)

Description of the Job	Price
1) Replace pump (3363394)	\$135.00
2) Replace fill valve (CW151, for most)	108.00
3) Replace timer knob (see belt drive)	78.00
4) Install two speed motor (389248)	230.00
5) Install timer	190.00
6) Spin drive assembly (9285761 and others)	240.00
7) Repair hose or drain fitting leaks	95.00
8) Replace sheared drive block	145.00
9) Replace lid safety switch (285671)	128.00
10) Replace sheared motor coupling (285743)	125.00
11) Replace transmission	265.00
12) Repair bleach dispenser hose	95.00
13) Rebuild agitator cam (285746)	118.00
14)	
15)	
16)	

Whirlpool Direct-Drive Washers
(Kenmore, KitchenAid, Roper & In-Sink-Erator)

Description of the Job	Price
1) Replace pump (3363394)	\$135.00
2) Replace fill valve (CW151, for most)	108.00
3) Replace timer knob (see belt drive)	78.00
4) Install two speed motor (389248)	230.00
5) Install timer	190.00
6) Spin drive assembly (9285761 and others)	240.00
7) Repair hose or drain fitting leaks	95.00
8) Replace sheared drive block	145.00
9) Replace lid safety switch (285671)	128.00
10) Replace sheared motor coupling (285743)	125.00
11) Replace transmission	265.00
12) Repair bleach dispenser hose	95.00
13) Rebuild agitator cam (285746)	118.00
14)	
15)	
16)	

General Electric Washers
(GE & Hotpoint)

Description of the Job	Price
1) Unjam pump (from inside tub)	\$79.00
2) Unjam pump (by opening up pump)	98.00
3) Replace pump (WH23X42)	148.00
4) Replace belt (WH1X2026)	95.00
5) Replace drive web	95.00
6) Replace tub boot (WH8X246)	145.00
7) Repair outer tub leak	135.00
8) Replace timer	195.00
9) Replace two-speed clutch with a single speed (WH49X231)	189.00
10)Install a two-speed clutch (WH49X265)	240.00
11)Install a new motor and switch (WH20X52 and others)	235.00
12)Replace water valve (CW151)	98.00
13)Replace agitator drive spline (WH1X1944)	98.00
14)Replace upper tub gasket (WH8X305)	130.00
15)	
16)	
17)	

General Electric Washers
(GE & Hotpoint)

Description of the Job	Price
1) Unjam pump (from inside tub)	\$79.00
2) Unjam pump (by opening up pump)	98.00
3) Replace pump (WH23X42)	148.00
4) Replace belt (WH1X2026)	95.00
5) Replace drive web	95.00
6) Replace tub boot (WH8X246)	145.00
7) Repair outer tub leak	135.00
8) Replace timer	195.00
9) Replace two-speed clutch with a single speed (WH49X231)	189.00
10)Install a two-speed clutch (WH49X265)	240.00
11)Install a new motor and switch (WH20X52 and others)	235.00
12)Replace water valve (CW151)	98.00
13)Replace agitator drive spline (WH1X1944)	98.00
14)Replace upper tub gasket (WH8X305)	130.00
15)	
16)	
17)	

